

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155747		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 08/08/2011	
NAME OF PROVIDER OR SUPPLIER  WOODCREST NURSING CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 1300 MERCER AVE DECATUR, IN46733			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K0000	<p>A Life Safety Code Recertification and State Licensure Survey was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a).</p> <p>Survey Date: 08/08/11</p> <p>Facility Number: 000556 Provider Number: 155747 AIM Number: 100290130</p> <p>Surveyor: Amy Kelley, Life Safety Code Specialist</p> <p>At this Life Safety Code survey, Woodcrest Nursing Center was found not in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2.</p> <p>This one story facility was determined to be of Type V (111) construction and was fully</p>			K0000	<p>Attached is Woodcrest's Plan of Correction for our annual Life Safety survey conducted on August 8, 2011. The attached plan of correction is our credible allegation of compliance. Preparation and/or execution of this plan of correction in general, or this corrective action in particular does not constitute an admission or agreement by Woodcrest of the facts alleged or conclusions set forth in the statement of deficiencies. This plan of correction and specific corrective actions are prepared and/or executed in compliance with Life Safety Code.</p>		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155747		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 08/08/2011	
NAME OF PROVIDER OR SUPPLIER  WOODCREST NURSING CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 1300 MERCER AVE DECATUR, IN46733			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K0029 SS=E	<p>sprinklered. The facility has a fire alarm system with smoke detection in corridors, areas open to the corridors and resident rooms. The facility has a capacity of 143 and had a census of 116 at the time of this survey.</p> <p>Quality Review by Robert Booher, Life Safety Code Specialist-Medical Surveyor on 08/10/11.</p> <p>The facility was found not in compliance with the aforementioned regulatory requirements as evidenced by the following:</p> <p>One hour fire rated construction (with ¾ hour fire-rated doors) or an approved automatic fire extinguishing system in accordance with 8.4.1 and/or 19.3.5.4 protects hazardous areas. When the approved automatic fire extinguishing system option is used, the areas are separated from other spaces by smoke resisting partitions and doors. Doors are self-closing and non-rated or field-applied protective plates that do not exceed 48 inches from the bottom of the door are permitted. 19.3.2.1</p> <p>Based on observation and interview, the facility failed to ensure 1 of 1 roll down doors at</p>			K0029	<p>1. What corrective action(s) will be accomplished for those residents found to have been affected by the deficient practice?</p>		09/19/2011

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155747		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 08/08/2011	
NAME OF PROVIDER OR SUPPLIER  WOODCREST NURSING CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 1300 MERCER AVE DECATUR, IN46733			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	<p>the openings in the kitchen wall, a hazardous area, would self close upon activation of the fire alarm system. This deficient practice could affect all residents in the main hall dining room.</p> <p>Findings include:</p> <p>Based on observation with Maintenance Technician # 1, Maintenance Technician # 2, Maintenance Lead and the Environmental Service Supervisor on 08/08/11 at 1:35 p.m., the main dining room was open to the corridor and met the requirements for a space to be allowed to be open to the corridor. The wall around the dining room is therefore, considered to be the corridor wall. There was a pass through opening in the corridor wall between the dining room and the kitchen. The opening was protected with a rolling door. Based on interview with Maintenance Director at the time of observation, the rolling door does not close upon activation of the fire alarm.</p> <p>3.1-19(b)</p>				<p>In an effort to correct this deficient practice, the pass through opening in the corridor wall between the dining room and the kitchen will have the rolling door connected to the fire panel so the rolling door will close upon activation of the fire alarm.</p> <p>2. How other residents having the potential to be affected by the same deficient practice will be identified and what corrective action(s) will be taken?</p> <p>In an effort to prevent residents from being affected by this deficient practice, the deficient practice has been corrected by connecting the rolling door to the fire panel. There are no other pass through doors in the facility.</p> <p>3. What measures will be put into place or what systemic changes will be made to ensure that the deficient practice does not recur? The deficient practice cannot recur as the pass through rolling door has been connected to the fire panel and there are no other pass through rolling doors in the facility.</p> <p>4. How the corrective action(s) will be monitored to ensure the deficient practice will not recur? What quality assurance programs will be put into place? Fire drills are held monthly and closure of the pass through door will be monitored by the maintenance</p>		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155747		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 08/08/2011	
NAME OF PROVIDER OR SUPPLIER  WOODCREST NURSING CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 1300 MERCER AVE DECATUR, IN46733			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K0038 SS=E	<p>Exit access is arranged so that exits are readily accessible at all times in accordance with section 7.1. 19.2.1</p> <p>Based on observation and interview, the facility failed to ensure exit access was arranged so 2 of 7 exits were readily accessible at all times in accordance with LSC Section 7.1. LSC Section 7.1 requires that means of egress for existing buildings shall comply with Chapter 7. LSC Section 7.7.1 requires all exits shall terminate directly at a public way or at an exterior exit discharge. Yards, courts, open spaces, or other portions of the exit discharge shall be of required width and size to provide all occupants with a safe access to a public way. In addition to providing the required width to allow all occupants safe access to a public way, such access also needs to meet the requirements with respect to maintaining the means of egress free of obstructions that would prevent its use, such as snow and the need</p>			K0038	<p>man monthly tio ensure closure of tihe door when tihe fire alarm is activated Monitoring will be ongoing with resultis tio QA time7 montihis</p> <p>1. Whati corrective action(s) will be accomplished fior tihose residenti fiond tio have been affected by tihe deficienti practice In an efiorti tio correcti tihis deficienti practice, tiemporary sidewalks have been instialled leading tio a public way firom tihe A and C wing</p> <p>2. How otlier residentis having tihe potential tio be affected by tihe same deficienti practice will be identified and whati corrective action(s) will be tiaker? No residentis will be affected by tihis deficienti practice as tiemporary walkways are in place leading tio a public way and will be replaced with permanenti walkways withir60 days.</p> <p>3. Whati measures will be puti intio place or whati systemiic changes will be make tio ensure tihati tihe deficienti practice does noti recur? Temporary walkways have been instialled and will be replaced with permanenti walkway leading tio tihe public way within60 days ensuring tihis deficienti practice does noti recur.</p> <p>4. How tihe corrective action(s) will be monitored tio ensure</p>		08/23/2011

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155747		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 08/08/2011	
NAME OF PROVIDER OR SUPPLIER  WOODCREST NURSING CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 1300 MERCER AVE DECATUR, IN46733			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	<p>for its removal in some climates or soft ground during heavy periods of rain. This deficient practice could affects all occupants evacuated through the exits at the end of both A and C wings.</p> <p>Findings include:</p> <p>Based on an observation with Maintenance Technician # 1, Maintenance Technician # 2, Maintenance Lead and the Environmental Service Supervisor on 08/08/11 at 12:15 p.m. and then again at 12:55 p.m., due to the construction of a new rehabilitation wing, the sidewalk was removed from the egress path at the exit at the end of both A and C wings. The excavation of this area has created large mounds of dirt and holes. The distance from the public way to A wing sidewalk is one hundred feet. The distance from C wing is sixty feet. Measurements were provided by Maintenance Technician # 1 at the time of observations.</p> <p>3.1-19(b)</p>				<p>the deficient practice will not recur what quality assurance programs will be put into place</p> <p>No monitoring needed as sidewalks to public ways are permanent once installed</p>		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155747		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 08/08/2011	
NAME OF PROVIDER OR SUPPLIER  WOODCREST NURSING CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 1300 MERCER AVE DECATUR, IN46733			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K0045 SS=E	<p>             Illumination of means of egress, including exit discharge, is arranged so that failure of any single lighting fixture (bulb) will not leave the area in darkness. (This does not refer to emergency lighting in accordance with section 7.8.) 19.2.8              Based on observation and interview, the facility failed to ensure the failure of any single fixture or bulb would not leave the area in darkness at 2 of 7 exits. This deficient practice could affect any number of residents, staff and visitors evacuated using the exits located at the end of wings A and C in the event of an emergency.              Finding include:              Based on an observation with Maintenance Technician # 1, Maintenance Technician # 2, Maintenance Lead and the Environmental Service Supervisor on 08/08/11 at 12:20 p.m. and then again at 12:57 p.m., the exterior exit discharge for wings A and C was equipped with a single light fixture with a single bulb. Based on an interview with Maintenance Technician # 1 at the time of observation, additional lights for these exit discharge           </p>			K0045	<p>             1. What corrective action(s) will be accomplished for those residents found to have been affected by the deficient practice? In an effort to prevent residents from being affected by this deficient practice, construction light is connected to the generator will be temporarily used for approximately 60 days equal to one foot candle to prevent areas of darkness along the walkways from A and C wing leading to the public way.              2. How other residents having the potential to be affected by the same deficient practice will be identified and what corrective action(s) will be taken? No resident has the potential to be affected by this deficient practice as walkways have been lit and no other walkways were affected by the construction project.              3. How other residents having the potential to be affected by the same deficient practice will be identified and what corrective action(s) will be taken? The construction lights are hooked to the generator and the permanent lighting will be connected to the generator which is self-tied weekly.           </p>		08/23/2011

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155747		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 08/08/2011	
NAME OF PROVIDER OR SUPPLIER  WOODCREST NURSING CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 1300 MERCER AVE DECATUR, IN46733			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE	
K0130 SS=E	<p>paths were located in the parking lot but due to the addition of the Rehabilitation wing the parking lot and lights were removed in the excavation process.</p> <p>3.1-19(b)</p> <p>OTHER LSC DEFICIENCY NOT ON 2786</p> <p>Based on record review and interview, the facility failed to ensure 1 of 6 water heaters had a current inspection certificate to ensure the water heater was in safe operating condition. NFPA 101, in 19.1.1.3 requires all health facilities to be maintained and operated to minimize the possibility of a fire emergency requiring the evacuation of residents. This deficient practice could affect any resident near the B wing mechanical room.</p> <p>Findings include:</p> <p>Based on record review with Maintenance Technician # 1, Maintenance Technician # 2, Maintenance Lead and the</p>		K0130	<p>with full load monthly</p> <p>How the corrective action(s) will be monitored to ensure the deficient practice will not recur, what quality assurance programs will be put into place?</p> <p>The generator is self tested weekly to ensure lights are operating even with loss of power. Documentation will be done by the maintenance man monthly and results to QA times 7 months.</p> <p>1. What corrective action(s) will be accomplished for those residents found to have been affected by the deficient practice? In an effort to prevent this deficient practice from affecting residents, the water heaters were inspected on August 17 to ensure safe operating condition.</p> <p>2. How other residents having the potential to be affected by the same deficient practice will be identified and what corrective action(s) will be taken? In an effort to prevent residents to be affected by this deficient practice all water heaters were inspected to ensure safe operating condition. Inspections are current in the nursing facility and maintenance is awaiting the certificate to be emailed.</p> <p>3. How the corrective action(s) will be monitored to ensure</p>		08/26/2011	

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155747		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 08/08/2011	
NAME OF PROVIDER OR SUPPLIER  WOODCREST NURSING CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 1300 MERCER AVE DECATUR, IN46733			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	<p>Environmental Service Supervisor on 08/04/11 at 12:35 p.m., the B wing mechanical room water heater with registration tag number 260343 had a Certificate of Inspection which expired on 05/26/11. Based on an interview with the Maintenance Technician # 1 at the time of record review, he was unable to provide a current certificate for this water heater.</p> <p>3.1-19(b)</p>				<p>the deficient practice will not recur what quality assurance programs will be put into place</p> <p><b>In an effort to prevent this deficient practice from recurring, the water heaters were placed on the PM schedule.</b></p> <p>4. How the corrective action(s) will be monitored to ensure the deficient practice will not recur what quality assurance programs will be put into place</p> <p><b>The PM schedule will be monitored monthly by the lead maintenance man to ensure the water heaters are inspected and the certificate indicates current inspection dates This QA will be ongoing with results to QA times 7 months</b></p>		